Appendix A

Previously Incurred Costs for BIA 33 Improvements or Repairs

Fiscal Year(s)	Amount	Source	Location	Description
FY2010 - FY2012	$60,000	TTP	South Section, from Manderson to US18	Topographic Survey and Conceptual Alignment & Profile
FY2010	$950,000	TTP	Middle Section, from BIA 14 to Manderson	Asphalt Patches and Overlay
FY2012	$150,000	TTP	North Section, from Rockyford to BIA 14	Asphalt Patches
FY2019	$50,000	BIA Road Maintenance	South Section, from Manderson to US18	BIA 33 – Road Repairs
FY2019	$122,000	TTP	North Section, from Rockyford to BIA 14	2019 Emergency Asphalt Pavement Repair
FY2020	$425,000	TTP / ERFO	North Section, from Rockyford to BIA 14	2020 Asphalt Pavement Repairs
FY2019 - FY2024	$2,138,400	TTP / TA / TTPSF	Middle Section, from Head Start to 0.9 miles to Oglala Lakota College Center	Manderson Pathway and Manderson Pathway Lighting and Safety Enhancements
FY2022 - FY2023	$63,000	TTP	North Section, 5.5 miles south of Rockyford, SD	BIA 33 Culvert Replacement, PS&E Development
FY2023	$150,000	TTP	North Section, 5.5 miles south of Rockyford, SD	BIA 33 Culvert Emergency/Temporary Repair